

## Bottle/Glass Filler Adjustment



If a Bottle Filler unit (Acorn Powell code: BFBV) appears not to be working correctly, please first check that the adjustment screw is set to achieve the desired water flow. Undo the nut (centre of image above), taking care not to lose the button which fits inside the nut (button is at left of image). Then adjust the flow rate with a screwdriver by turning the screw fitting by  $\frac{1}{4}$  turns.